




Curva termoformata R=1,5D 45°
 Thermoformed bend R=1,5D 45°
 Courbe termoformé R=1,5D 45°
 Waermegeformte Boegen R=1,5D 45°



\varnothing	z	b
mm	mm	mm
50	40	35
63	46	43
75	54	51
90	63	58
*110	80	70
*125	89	79
*140	98	87
*160	119	99
*200	143	122

*PN12,5